

Bode Analyzer Suite 3.52

Bugfixes from version 3.51SR1 to 3.52

Bug ID	Description
344643	Device locking ":SYST:LOCK:REQ?" doesn't always work for Bode 500.
353385	Update issue when repeating circuit fit multiple times. Results not updated.
353496	A corrupt data point caused the entire trace to disappear from the chart.
371577	Potential crash during Internal Device Calibration on damaged Bode 100.

Known Issues

Known issues in **Bode Analyzer Suite 3.52** that will be resolved in future:

Bug ID	Description	Current workaround
381795	DUT settling time limited to 10 s	-