

Bode Analyzer Suite 3.23

Bugfixes from version 3.22 to 3.23

Bug ID	Description
146986	BAS sometimes freezing when closing
145727	Automation Interface: Results are NaN in ExternalCoupler , ExternalBridge and Impedance Adapter modes
147216	BAS can crash during software-disconnect of Bode device
149415	Plugins not loaded correctly in case of corrupted config file

Known Issues

This is a list of known issues in BAS 3.23 that will be resolved in the next version:

Bug ID	Description	Current workaround
-	-	-