

Bode Analyzer Suite 3.25 SR2

Bugfixes from version 3.25 SR1 to 3.25 SR2

Bug ID	Description
247497	Anti-Aliasing can't be disabled because level in options can't be set to zero
247708	BAS sometimes crashes during measurement initialization

Known Issues

Known issues in **Bode Analyzer Suite 3.25 SR2** that will be resolved in future:

Bug ID	Description	Current workaround
184547	Recalculate measurement trace values retroactively can lead to deviation at frequencies below 100 Hz	Don't use feature "Recalculate measurement trace values" for measurement data below 100 Hz

Known issues in **Automation Interface 3.25 SR2** that will be resolved in future:

Bug ID	Description	Current workaround
-	-	-